



## Vehicle Inspection Report

Date	13-10-20	
Buyer	John	
Phone	0432 567 344	
Seller	Sydney Motor Group	
Phone	9778 1356	
Make	Honda	
Model	CR-V	
Badge/ Series	Limited Edition	
Colour	Silver	
Comply/Build Date	Aug-11	Jul-11
Registration No	BDB 72Y	
Rego Expiry Date	<b>Unregistered</b>	
Kilometer Reading	134,166	
Vin/ Serial Number	MRHRE47307P082438	
Engine Number	E2648597123	

### Abbreviations:

**P/S** Passenger Side

**D/S** Driver's Side

**D/S/F** Driver's Side Front

**D/S/R** Driver's Side Rear

**Minor Repairs**

**Recommended Repairs**

**Immediate Repairs**

		ENGINE	OK	NO	Comments
1		Engine Idle	*		
1a		Engine Oil Condition	*	X	Dirty
2		Engine oil leaks	*		
3		Fumes/Smoke	*		
4		Engine Main Seals	*		
5		Rocker Cover Gasket	*		
6		Engine Sump Gasket	*		
7		Fluid Levels	*		
8		Engine Mounts	*		
9		Emission controls	*		
10		Drive belts & pulleys	*		
11		Fan (Electric)	*		
12		Hoses/Pipes	*		
13		Fuel system (injectors)	*		
14	NA	below)			
15	NA	Turbo/Intercooler			

16		Inlet Manifold leaks	*			
17		Engine noises	*			
18	NA	Compression Test				

Usually, timing belts can't be physically checked. You must refer to the manufacturer's specifications in order to confirm replacement times.

**Additional Comments**

Service due at 129,000 kms (now overdue)

TRANSMISSION/ GEARBOX			OK	NO	Comments
19		Operation	*		
20	NA	Clutch (Man)			
21		Inhibitor Switch (Auto)	*		
22	NA	Gear Linkages (Man)			
23		Gear Shifting (Auto)	*		
24		Mountings	*		
24a		Auto Fluid Condition	*		
25		Auto Pan Gasket	*		
25a		Fluid/Oil leaks	*		
26		Noises	*		
27		Transfer Case (4x4 or AWD)	*		

**Additional Comments**


ELECTRICAL SYSTEM			OK	NO	Comments
28		Charging System	*		Charging Voltage 13.85
29		Ignition system	*		
30		Ignition Barrel/ Key(s)	*		1 Check for 2nd key
32		Battery Condition	*		
33		Battery Cables/Terminals	*		
34		Starter motor cranking	*		
35		Injectors	*		
36		Headlights	*		
37		Tail lights	*		
38		Blinkers	*		
39		Brake Lights	*		
40		Parking lights	*		
41		Number Plate Lights	*		
42		Hazard Lights	*		

43		Horn	*			
44		Power Windows	*			
45		Central locking/remotes	*			
46		Power mirrors	*			
47		Window wipers & washers	*			
48	NA	Sunroof (softtop)				
49	NA	Fog/driving lights (front & rear)				
50		Alarm (immobiliser)	*			
51	NA	Electric Seats (D/S Front only)				

**Additional Comments**


AIR CONDITIONING			OK	NO	Comments
52		Operation	*		Cold
53		Condenser	*		
54		Compressor	*		
55		Pipes/ Hoses	*		
56		Gas	*		
57		Belts	*		
58		Leaks	*		

**Additional Comments**


COOLING SYSTEM			OK	NO	Comments
59		Radiator & cap	*		
60		Hoses & pipes	*		
61		Water pump & fan	*		
62		Radiator coolant level	*		
63		Inhibitor/coolant concentration	*		Strong
64		Leaks	*		
65		Pressure Test	*		

**Additional Comments**


EXHAUST SYSTEM			OK	NO	Comments
----------------	--	--	----	----	----------

66		Catalytic Converter Function	*			
67		Mufflers x 2	*			
68		Exhaust Manifold	*			
69		Exhaust Pipes x2	*			
70		Tailpipe(s)	*			
71		Brackets/ Fittings	*			
72		Leaks	*			

**Additional Comments**


STEERING & SUSPENSION			OK	NO	Comments
73		Front suspension/shocks	*		
74		Rear suspension/shocks	*		
75		Wheel bearings	*		
76		Drive shafts, Boots, & Uni	*		
77		Ball Joints/ Tie Rod Ends	*		
78		Rack & Pinion/ Steering Box	*		
79		Sway Bar/Control Arm	*		

**Additional Comments**


BRAKES			OK	NO	Comments
80		Master cylinder/ booster	*		
81		Brake Pedal	*		
82		Brake callipers	*		
83		Hoses & pipes	*		
84		Front brake pads	*		70 % remaining
85		Rear brake pads	*		40 % remaining
86		Front Brake Rotors	*		
87		Rear brake rotors	*		
88	NA	Rear Wheel cylinders	*		
89		Hand brake	*		
90		Brake Fluid Moisture Content	*		<1%

**Additional Comments**


TYRES & WHEELS			OK	NO	Comments			
91		Front Tyre Condition	*	✘ ✘	D/S	30	P/S	10 Remaining
92		Rear Tyre Condition	*		D/S	70	P/S	70 Remaining
93		Spare Tyre (space saver)	*		100			
94	Na	Alloy Wheel Condition	*					
95		Rims/Wheel caps						

**Additional Comments**

P/S/F tyre (worn on outside edge)

UNDERBODY			OK	NO	Comments			
96		Sub frame/ members	*					
97		Mounting points	*					
98		Under floor panels	*					
99		Fuel tank & hoses	*					
100		Transaxle	*					

**Additional Comments**


INTERIOR			OK	NO	Comments			
101		Seats (front/rear)	*					
102		Seat belts/mountings	*					
103		Headlining	*	✘	Dirty			
104		Interior lights	*					
105		Carpets (front/rear)	*					
106		Floor mats (front & rear)	*					
107		Door panels	*					
108		Door trims	*					
109		Floor/Kick panels	*					
110		Door handles (inner)	*					
111		Rear boot	*					
112		Dash pad	*					
113		Glove box	*					
114		Headrests	*					
115		Rear view mirror	*					
116		Door locks/hinges	*					
117		Door rubbers	*					

118		Door warning light	*			
119		Window operation	*			
120		ABS Warning Light	*			
121		SRS Warning Light	*			
122		Dash warning lights/gauges	*			
123		Electric fan	*			
124		Heater/demister	*			
125		Radio/CD	*			
126		Aerial	*			
127		Sound Equipment/Speakers	*			
128		Onboard computer (trip)	*			
129	NA	Satellite Navigation System				
129a	NA	Bluetooth Phone				
130		Electronic Stability Control	*			
131	NA	Rear Parking Sensors				
131a	NA	Rear camera				
132		Lights/blinkers	*			
133		Rear demister	*			
134		Cigarette lighter	*			
135		Bonnet release (cable)	*			
136		Petrol lid (auto/ manual)	*			
137		Boot release (auto/ manual)	*			
138		Steering Wheel (adjustable)	*			
139		Tool kit	*			

**Additional Comments**

Dirt stains on head lining

Additional Features		OK	NO	Comments
<b>Communication</b>				
	Bluetooth	*		
	Multi Function Screen	*		
	Apple/Android Car Play			
	CD/DVD Player	*		
	Voice Recognition			
<b>Safety &amp; Security</b>				
	Seat Belts - Pretensioners	*		
	Crash Avoidance with Braking			
	Cruise with Distance Control			
	(reversing)			
	Bonnet - Active Safety			
	Traction Control			
	Electronic Stability Control			
	Hill Decent			
	Hill Holder			
	Distribution (EBD)	*		
	Alert Warning - Collision Fwd			

	Blind Spot Monitor/Sensor	Green	Yellow	Orange	Red
	Corner Braking	Green	Yellow	Orange	Red
	Lane Departure Warning	Green	Yellow	Orange	Red
	Park Distance Alert (Fr & R)	Green*	Yellow	Orange	Red
	Display	Green	Yellow	Orange	Red
	Steering	Green	Yellow	Orange	Red
	Rear Camera	Green*	Yellow	Orange	Red
	Front Camera	Green	Yellow	Orange	Red
	Side Camera	Green	Yellow	Orange	Red
	<b>Comfort &amp; Convenience</b>				
	Keyless Start - FOB Prox related	Green	Yellow	Orange	Red
	Starter Button	Green	Yellow	Orange	Red
	Central Locking (once mobile)	Green	Yellow	Orange	Red
	<b>Lights &amp; Windows</b>				
	High Beam Auto Dipping	Green	Yellow	Orange	Red
	Automatic (light sensitive)	Green	Yellow	Orange	Red
	Electric Level Adjustment	Green	Yellow	Orange	Red
	Headlights - Active Cornering	Green	Yellow	Orange	Red
	Headlight Washers	Green	Yellow	Orange	Red
	Rain Sensor (Auto wipers)	Green	Yellow	Orange	Red
	Rear Wiper/Washer	Green	Yellow	Orange	Red
	<b>Seating</b>				
	Front Seats (electric)	Green*	Yellow	Orange	Red
	Front Seats (heated)	Green	Yellow	Orange	Red
	Driver with Electric Lumbar	Green	Yellow	Orange	Red
	Passenger with Elec Lumbar	Green	Yellow	Orange	Red
	<b>Instruments &amp; Controls</b>				
	Digital Instrument Display	Green	Yellow	Orange	Red
	Tyre Pressure Monitoring	Green	Yellow	Orange	Red
	GPS (Satellite Navigation)	Green*	Yellow	Orange	Red
	Speed Limiter	Green	Yellow	Orange	Red
	Engine Start/Stop when Idle	Green	Yellow	Orange	Red
	Park Brake - Electric	Green	Yellow	Orange	Red
	Head Up Info Display (HUD)	Green	Yellow	Orange	Red
	Ride Height - electronic	Green	Yellow	Orange	Red
	<b>Exterior</b>				
	Power - Tailgate/Boot	Green	Yellow	Orange	Red
	Remote Boot/Hatch Release	Green	Yellow	Orange	Red
	Door Mirrors - Electric/Folding	Green*	Yellow	Orange	Red
	Door Mirrors - Elec with Memory	Green	Yellow	Orange	Red
	Door mirrors (auto dipping)	Green	Yellow	Orange	Red
	Spoiler - Diffuser on Rear	Green	Yellow	Orange	Red
	Spoiler - Rear Roof Mounted	Green	Yellow	Orange	Red
	<b>Transmission &amp; Drivetrain</b>				
	Gear Shift Paddles bh S/Wheel	Green	Yellow	Orange	Red
	Driving Mode - Selectable	Green	Yellow	Orange	Red
	Centre Differential - Active	Green	Yellow	Orange	Red
	Electronic Differential Lock	Green	Yellow	Orange	Red
	<b>Steering</b>				
	Multi-function Steering Wheel	Green*	Yellow	Orange	Red

		Steering Wheel - Sports				
		P/Steering - Electric Assist				
		P/Steering - Speed Sensitive				

EXTERIOR		OK	NO	Comments
140		Bonnet/ Boot Struts & Locks	*	
141		Door Handles & Locks	*	
142		Door Moulds	*	
143		Door mirrors	*	
144		Door pillars	*	
145		Windscreen (F & R)	*	
146		Windows & Trims	*	
147		Wiper rubbers (F & R)	*	
148		Chassis & Rails	*	
149		Inner guards	*	
150		Front grill	*	
151		Roof rack (rails)	*	
152		Head lights	*	
153		Tail lights	*	
154		Blinkers	*	
155		Number plates	*	
156	NA	Tow bar (and plug)	*	
157		Badges	*	
158		Mud flaps (front & rear)	*	

**Additional Comments**


BODY CONDITION & PAINTWORK		Ums	NO	Comments	
159		D/S/F Guard	100	X X	Dent
160		D/S/F Door	100	X	Mark & scratch
161		D/S/R Door	100		Scratches
162		D/S/R ¼ Panel	100		
163		Rear bumper bar		X	Damaged on D/S/R corner
164		Rear Boot/hatch	110		
165		P/S/R ¼ Panel	100		
166		P/S/R Door	100		
167		P/S/F Door	100		Mark on P/S/F door
168		P/S/F Guard	100		
169		Front bumper bar		X	Scrapes on D/S/F bumper
170		Front bonnet	110	X X	Scratches & large ding
171		F & R Spoilers			
172		Side skirts			



173	Roof	100			
-----	------	-----	--	--	--

**NOTE: Paint Thickness measured in micron units (Ums)**

**Additional Comments**

Large dent on D/S/F guard
Mark & scratch on D/S/F door
Scratches on D/S/R door
Damaged on D/S/R bumper
Scrapes on D/S/F bumper
See Body Inspection File to view photos of damage

ROAD TEST		OK	NO	Comments
174	Engine performance	*		
175	Exhaust smoke	*		
176	Transmission/ gearbox	*		
177	Differential/ drive train	*		
178	Steering/ suspension	*		
179	Braking/ pedal operation	*		
180	Speedo operation	*		
181	Cruise control	*		

182	Car Performance	Poor	Fair	Good	V.Good	Excellent
183	Engine	Misfire	Rough	Uneven	Even	Smooth
184	Acceleration	Poor	Fair	Good	V.Good	Excellent
185	Handling	Poor	Fair	Good	V.Good	Excellent
186	Ride	Soft	Hard	Normal	Smooth	V.Smooth
187	Overall condition for age/kms	Poor	Fair	Good	V.Good	Excellent

**Note: Criteria is ranked for the vehicle make, model, age, and kms.**

**Additional Comments**


**LOG BOOKS & SERVICING**

Log Book supplied	Yes	No			
Log Book stamped	Yes	No	Partially		
Additional receipts supplied	Yes	No			
Car regularly serviced	Yes	No	Intermittent		
Last Service ( <i>stamped in Log Book</i> ) at	Date	28-11-2018	at	113,853	Kms
Last Service ( <i>not stamped in Log Book</i> ) at	Date		at		Kms
Next service due at	Date	1-08-2019	at	129,000	Kms

Last service not done or stamped in Log Book
Service is now overdue


**REPAIRS NEEDED (as listed above)**

	<b>Immediate Repairs (or within 3 mths)</b>	<b>Action Required</b>	<b>Photos Page</b>
1	Check for 2nd key	Ask dealer	
2	P/S/F tyre (worn on outside edge)	Replace	
3	Service due at 129,000 kms (overdue)	Service	See Log Book
4	Check for registration renewal by dealer (3, 6, or 12 mths)	Re-register	

	<b>Recommended Repairs (within 6-12 months or at next service interval)</b>	<b>Action required</b>	<b>Photos Page</b>
5	2 x rear head rests (missing)	Replace	71

	<b>Minor Repairs (after 12 months but monitor at each service)</b>	<b>Action Required</b>	<b>Photos Page</b>
6	Dirt stains on head lining	Clean	101-104
7	D/S/R bumper damaged	Repair/repaint	124-126
8	Large dent on D/S/F guard	Repair/repaint	114,115
9	Marks & scratches on panels	Buff or touchup	116-123
10	Scraped on D/S/F bumper	Touchup	135
11	Scratches & large ding on front bonnet	Repair/repaint (or remove using PDR system)	140-144

**Note:**  
All of our inspections are based on a physical description of what is seen and heard by us. We do not advise on the precise value

of the vehicle or authenticate its origin. We are not responsible for any problems that can occur after an inspection is completed. However, Sydney Auto Inspections guarantees each inspection to be accurate at the time the vehicle is inspected. Physical and mechanical damage can occur between the time a vehicle is inspected and when the vehicle is actually purchased. Therefore, we cannot be held responsible for those occurrences should they ever happen. Any guaranties or warranties implied or not on any vehicle inspected by Sydney Auto Inspections is strictly with the seller of that vehicle.

**If you need to discuss any item in this report, then please contact:**

**Peter 0402 408 936**



Sydney Auto Inspections  
86 High St  
Carlton NSW 2218

































